



Product Service

**Choose certainty.  
Add value.**

TÜV SÜD Product Service GmbH • Ridlerstraße 65 • 80339 Munich • Germany

American Rescue Technology, Inc.  
2780 Culver Ave,  
Kettering, OH 45429  
USA

Your ref./from	Our ref./Name	Phone-ext/E-Mail	Fax-ext	Date	Page
	T1-dg Gerhard David	+49 89 5008-4175 gerhard.david@tuev-sued.de	+49 89 5008-4239	2007-06-25	1 of 2

## CONFIRMATION

SINGLE - coupling

One Step Coaxial coupler "**OSC® - coupler**"

have been tested according to NFPA 1936, Standard on Powered Rescue Tools, 2005 Edition.

Tests have been done for

American Rescue Technology, Inc.  
2780 Culver Ave,  
Kettering, OH 45429  
USA

Test result: The examination of the products resulted into a positive conclusion. The essential requirements according to the mentioned technical directives and standards are fulfilled.

Trade Register Munich  
HRB 85742  
V.A.T. DE 129484267  
HypoVereinsbank Munich  
Acc.No. 48 852 211  
Bank Code 700 202 70

Chairman of the Board:  
Dr. Axel Stepken  
Managing Directors:  
Joachim Birnthal (CEO)  
Lothar Weihofen (CFO)

Phone: +49 89 5008-40  
Fax: +49 89 5008-4222  
[www.tuev-sued.de](http://www.tuev-sued.de)

TÜV SÜD Product Service GmbH  
Munich Branch  
Ridlerstraße 65  
80339 Munich  
Germany



Product Service

Test was done: June 20, 2007

Test report no. is 028-71308593-000

Test institute:  
TUV Süd Product Service GmbH  
Ridlerstraße 65  
80339 München  
GERMANY


Dear Madam/Sir,

Yours sincerely,

TÜV SÜD Product Service GmbH

A handwritten signature in blue ink, appearing to read 'Gerhard David', written over the printed name.

i.A. Gerhard David  
Trade & Retail 1



Trade Register Munich  
HRB 85742  
V.A.T. DE 129484267  
HypoVereinsbank Munich  
Acc.No. 48 852 211  
Bank Code 700 202 70

Chairman of the Board:  
Dr. Axel Stepken  
Managing Directors:  
Joachim Birnthal (CEO)  
Lothar Weihofen (CFO)

Phone: +49 89 5008-40  
Fax: +49 89 5008-4222

[www.tuev-sued.de](http://www.tuev-sued.de)

TÜV SÜD Product Service GmbH

Munich Branch  
Ridlerstraße 65  
80339 Munich  
Germany